

Texture Modification of the Shuttle Landing Facility Runway at the NASA Kennedy Space Center

Robert H. Daugherty and Thomas J. Yager
Langley Research Center, Hampton, Virginia

July 1996

National Aeronautics and
Space Administration
Langley Research Center
Hampton, Virginia 23681-0001

Texture Modification of the Shuttle Landing Facility Runway at the NASA Kennedy Space Center

Robert H. Daugherty and Thomas J. Yager
NASA Langley Research Center

SUMMARY

This paper describes the test procedures and the selection criteria used in selecting the best runway surface texture modification at the Kennedy Space Center (KSC) Shuttle Landing Facility (SLF) to reduce Orbiter tire wear. The new runway surface may ultimately result in an increase of allowable crosswinds for launch and landing operations. The modification allows launch and landing operations in 20-kt crosswinds if desired. This 5-kt increase over the previous 15-kt limit drastically increases landing safety and the ability to make on-time launches to support missions where space station rendezvous is planned. The paper presents the results of an initial texture modification in 1988 to reduce tire spin-up wear, then describes a series of tests using an instrumented ground test vehicle to compare tire friction and wear characteristics, at small scale, of a number of proposed texture modifications placed into the SLF runway surface itself. Based on these tests, three candidate surfaces were chosen to be tested at full-scale using a highly modified and instrumented transport aircraft capable of duplicating full Orbiter landing profiles. The full-scale Orbiter tire testing revealed that tire wear could be reduced approximately in half using either of two candidates. The texture modification technique using a Skidabrader™ shot-peening machine proved to be the most effective and thus the entire SLF runway surface was modified in September 1994. The extensive testing and evaluation effort that preceded the selection of this particular surface texture modification technique is described herein.

INTRODUCTION

Since the beginning of the Space Transportation System (STS) program, a need for a landing facility near the launch site of the Space Shuttle has existed. This need stems from the possibility of having to make a return-to-launch-site (RTLS) abort landing as well as a desire to make the Kennedy Space Center (KSC) Shuttle Landing Facility (SLF) a prime landing site for normal end-of-mission operations to reduce program cost, time, and ferry risk factors. Due to extreme conditions imposed on Orbiter tires during landing, especially the main gear tires, tire wear has been a long-standing issue for landings at KSC. The SLF runway was designed with extremely rough texture and transverse grooving to provide exceptional friction performance during heavy rainfall conditions. These factors combined with landing in the presence of crosswinds caused tire wear to be a limiting parameter for flight operations. Early landings of the Space Shuttle Orbiter were made on the lakebeds and smooth concrete runways at Edwards Air Force Base, CA, to allow the greatest margin possible for errors in the final approach for landing or for anomalies during the landing rollout. The KSC SLF in Florida has a unique runway constructed in the mid-1970's at a location approximately 5 miles from the Shuttle launch pads and provides the STS program with the capability to land safely in the event of an RTLS or poor weather conditions at other sites. Operationally, the prime landing site is the SLF, which minimizes program costs, reduces Orbiter processing time, and eliminates the hazards associated with ferry flights from the west coast.

Early in the STS program, excessive wear on the Orbiter main gear tires was observed during landing operations at the KSC SLF. Almost every landing at the SLF had some tire

wear anomaly that could be traced to the roughness of the surface. The original specifications for flight operations included the capability to land in 20-kt crosswinds, but tire wear concerns at the KSC SLF reduced the allowable landing crosswind limit to 10 kts. The 20-kt crosswind specification was to provide the STS program with the flexibility to launch and land without frequent delays due to weather. The unique Orbiter gear geometry, landing conditions, tire materials, and runway configuration all combined to produce tire wear that limited the Orbiter's crosswind landing capability. Numerous attempts to build operational capability up to the 20-kt crosswind level have been made, including changing the SLF runway touchdown zone texture and changing the tread material of the main gear tires.

In the mid 1980's, research was conducted to quantify the effect of various parameters such as speed, yaw angle, runway roughness, and load on the tire wear phenomenon. Yaw angle is defined as the angle between the rotational plane of a tire and its velocity vector. The results of those tests showed that the spin-up process produced an unacceptable wear spot on the main gear tires and that the spot grew with subsequent cornering later in the rollout whether it was crosswind- or pilot-induced. At that time, work was begun to improve the tire wear characteristics by changing the tread rubber compounding. In addition, work was conducted at the NASA Langley Research Center (LaRC) Aircraft Landing Dynamics Facility (ALDF) which showed that a large reduction in spin-up wear could be achieved by changing the texture in the spin-up regions of the runway (reference 1). The original texture of the runway was an extremely rough longitudinally-brushed finish with transverse grooving measuring 1/4 in. wide by 1/4 in. deep, spaced on 1 1/8 in. centers. A 3500-ft-long section on each end of the 15000-ft-long runway was modified to a new texture which resembled corduroy material with its texture aligned with the landing

direction. The texture was modified using a stack of diamond grinding wheels which cut into the original surface deeply enough to remove the original transverse grooves. This modification reduced the main gear tire spin-up wear levels to one-half of the original values. Thus the allowable crosswind value for landing, and therefore launching, was increased from 10 kts to 12 kts, but was still short of the original program requirement for 20-kt crosswind landing capability.

In 1992, mission STS-50 landed with the first main gear tires using a new tread compound. This new compound produced less tread wear and allowed crosswinds for launch and landing to be as high as 15 kts. Numerous studies were conducted to see what effect the surface roughness had on rollout wear as opposed to spin-up wear (references 2-4). Results of those studies showed that while the transverse grooves had a large effect on spin-up wear, they had little or no effect on the magnitude of the rollout wear response of the tire (reference 5). Conversely, the corduroy texture on the ends of the runway had a drastic effect on spin-up wear but caused the same amount of wear on the tire when rollout occurred on that surface. Thus, it became obvious that simply continuing the corduroy texture into the center 8000 feet of the runway would not produce the desired reduction in tire wear to allow for 20-kt crosswind operations.

The studies at NASA LaRC showed a relationship between tire wear and tire side energy. The relationship showed that to increase the tire wear capability up to a 20-kt crosswind level, the tire must be capable of absorbing twice the energy necessary for a 15-kt-crosswind condition.

The purpose of the study described in this paper was to define a texture modification for the SLF which would reduce the Orbiter main gear tire rollout wear rate by approximately

one-half while retaining acceptable wet friction performance . To do this, a plan was developed wherein a number of modification techniques were applied in small test strips directly on the runway surface at the KSC SLF. An Instrumented Tire Test Vehicle (ITTV) was used to rate 16 different textures applied to the runway surface in addition to the two existing textures. Comparison testing with the ITTV involved loading a T-38 aircraft main gear tire and conducting yawed-rolling tests at low speeds using a special instrumented fixture attached to the rear of the ITTV. Wear rate information in the form of lost weight per foot of rollout distance was used to classify each surface texture treatment. Wet friction test results were also used in conjunction with the wear information to narrow the surface selection to three candidates. These three surface treatments were then applied to “full-scale” test sections that encompassed the full length of the runway (15000 feet) and were about 10-12 feet wide. A specially modified Convair 990 transport aircraft was then used to conduct full-scale tests of Orbiter main gear tires on the candidate strips simulating Orbiter landings under a variety of conditions and piloting techniques, including simulated 20-kt crosswind landings. The results of the tests were used to select a modification technique to provide the necessary reduction in tire wear rates to allow for 20-kt crosswind operations. This paper presents the modification techniques studied, documents the results of the ITTV testing used to narrow the full-scale candidates down to a manageable number, and presents results of the Convair 990 aircraft full-scale tire tests which were used to select the modification technique which could provide a 20-kt crosswind landing capability for the Orbiter.

APPARATUS

Original Runway

The original runway surface, prior to any modifications for these tests, consisted of an extremely rough longitudinally-brushed finish with transverse grooving measuring 1/4 in.

wide by 1/4 in. deep, spaced on 1 1/8 in. centers (figure 1(a)). A 3500-ft-long section on each end of the 15000-ft-long runway was modified to a new texture which resembled corduroy material with its texture aligned with the landing direction (figure 1(b)).

Test Vehicles

Instrumented Tire Test Vehicle. The ITTV is a highly-modified 1976 truck (figure 2). The 28000-lb truck has a specially-designed force measurement dynamometer attached to the rear which permits the mounting of a wide range of aircraft and passenger vehicle tires or other apparatus for various kinds of testing. Aircraft tires up to 26 inches in diameter can be accommodated in the fixture and can be vertically loaded using a pneumatic system up to 5000 lb. The fixture can be yawed with respect to the direction of motion so that tire cornering data can be acquired. Forces and moments associated with yawed and/or braked rolling conditions such as side load, drag load, aligning torque, and overturning torque can be measured and recorded using an on-board electronic data acquisition system. Other pertinent data for tire testing including vehicle speed and distance are also measured. The ITTV can perform tests at any speed up to 65 mph. The vehicle operator and observer have numerous display devices to provide real-time feedback during testing in an attempt to maintain the desired test conditions throughout the test. Further information about the ITTV test capability can be found in references 6 and 7.

Landing Systems Research Aircraft. In 1989 NASA designed a test facility capable of simulating full-scale Orbiter landing conditions. The facility consists of a modified Convair 990 aircraft and is known as the Landing Systems Research Aircraft (LSRA) (figure 3). The LSRA program was funded by the NASA Shuttle Program Office at Johnson Space Center and provided the capability for full-scale testing of Orbiter main gear tires. Several other tire test facilities had various parameters such as vertical load

that could be tested at full scale but these facilities could not represent other full-scale effects correctly, such as a flat, concrete runway.

The development of the LSRA was undertaken at the NASA Dryden Flight Research Facility in Edwards, CA. The aircraft was highly modified, and required a large hole cut in the aircraft belly at the center-of-gravity location between the main landing gear. A robust structural modification was designed to carry aircraft fuselage loads around the hole to insure structural integrity throughout the aircraft. A hydraulic loading system was installed in the aircraft to apply vertical load to an articulating pallet to which the desired test article was attached (figure 4). The system was capable of applying up to 250000 lb of vertical load to the test article. For the present investigation, a steerable fixture with a single Orbiter main gear tire was attached to the pallet. The fixture was controlled using a sophisticated feedback control system which permitted time histories of vertical load and yaw angle to be input into an on-board control computer prior to a test flight. A typical set of time histories used by the control computer during a simulated 20-kt crosswind Orbiter landing is shown in figure 5. The fixture was steered hydraulically using a special rotary actuator capable of yawing the fixture up to 35 degrees per second. The desired speed time history was not incorporated into the feedback control system but an indicator was mounted in the cockpit of the aircraft to give the test pilot a comparison of how fast or slow the test article was compared to the desired speed time history. The steerable fixture was controlled in part by using a set of optical non-contact infra-red translational speed devices. These devices measure translational speed by looking at interference patterns of the radiation reflected by the ground. Because the pilot of the aircraft must steer the aircraft in response to the side forces generated by the test tire or due to the actual crosswinds on the test aircraft, a means of measuring the aircraft yaw angle (in this case, the angle between the aircraft body axis and its velocity vector) needed to be devised. Conventional inertial platform units do not

have the accuracy or the response needed for this application, so two of the optical units were mounted at ± 45 degrees from the body axis and 90 degrees to each other. The aircraft was defined to have zero yaw angle if both instruments agreed in their speed measurements. If one instrument reported a higher speed than its companion, the aircraft yaw angle could be computed in real time by the control computer and the steer angle of the fixture relative to the body axis could be appropriately adjusted. This ensured that test aircraft pilot inputs were isolated from the test tire yaw angles.

The test aircraft was capable of landing at speeds up to 245 kts and beginning a test at about 240 kts, if desired. The vertical load for the single tire test fixture was structurally limited to 150000 lb, which is slightly higher than the maximum desired test tire load of 142500 lb. The vertical load could be controlled to within approximately 2000 lb, the yaw angle accuracy was approximately 0.25 degrees, and the aircraft speed was generally held within 2-5 kts of the desired speed time histories.

Over 100 channels of data were recorded both on-board the aircraft and after telemetry to a ground control station. Some of the pertinent parameters recorded for this part of the investigation included aircraft speed, test tire vertical, side, and drag loads, test tire yaw angle, and tread temperature. Extensive video coverage of the test tire from three different locations also proved to be an invaluable measurement tool. The video signal was synchronized to the data stream and thus the time of exposure of different Orbiter tire carcass cord layers could be recorded in post-processing playback. This visual measurement of tire wear was one of the most widely-used pieces of information in this investigation. Numerous safety features were added to the aircraft for these tests, including low oxygen sensors to detect the presence of a nitrogen gas accumulator leak, fault-detection hardware and software in the computer and control system, fire detection and suppression systems, triple-redundant mechanisms to ensure cessation of load application

if needed, and armor plating of certain areas of the aircraft. A more detailed description of this unique test facility can be found in reference 8.

Test Tires

Instrumented Tire Test Vehicle Tests. The test tires used on the test fixture of the ITTV were 20 x 4.4 bias-ply Type VII aircraft tires with a ply-rating of 14 and a three-groove tread design and are similar to those found on the main gear of a T-38 aircraft.. A new and a worn ITTV test tire are shown in figure 6(a). The rated load and pressure of the tire are 6000 lb and 265 psi respectively. For wear testing it was desirable to have the test tire inflated to the actual Orbiter tire pressure so the ITTV test tires were inflated to 350 psi. The tires were mounted on standard aircraft wheels according to accepted build-up procedures. A new tire was used for each of the surfaces tested.

Landing Systems Research Aircraft Tests. The test tires used on the LSRA steerable test fixture were of the same design as the Orbiter main gear flight tires. These tires were 44.5 x 16.0 - 21 bias-ply aircraft tires with a 34-ply rating and are shown in figure 6(b). The original tire rated load and pressure were 60900 lb and 315 psi respectively. These test tires (and the flight tires) are generally inflated to higher values prior to flight due to some small expected leakage and the cold temperature expected during normal landing operations. Therefore these test tires were inflated to 340 psi at ambient temperature. The peak certified tire load at the time of this writing is 142500 lb. This load limit is to prevent excessive tire deflections during landing operations which could damage the carcass structure. The test tire is of the “modified” tire design in which an additional 0.1 inch of undertread was added to the original design and the entire tread material was changed from a natural rubber composition to a blend of natural and synthetic rubbers comparable to that used on commercial aircraft. These modified tires provide a much-

improved wear behavior as compared to tires of the original design. The tread grooves themselves are 3/32 in.. thick. A sketch of the tire cross-section is shown in figure 7.

The only difference between the test tires and actual flight tires is that the test tires failed certain government quality control tests due to cosmetic reasons. The manufacturer's certification of the tires for flight and all wear testing to date suggests that these "rejected" tires are fully as robust as those that make it to the flight vehicle. A new tire was used for each test run conducted on the full-scale test strips using the LSRA. The Orbiter tires were mounted on standard Orbiter beryllium brake-wheels according to accepted build-up procedures. The tire/wheel combination was mounted on a specially-designed axle, along with a standard Orbiter beryllium brake assembly, to allow it to be attached to the test fixture on the aircraft.

Other Test Equipment

Mu Meter. The Mu meter, shown in figure 8(a), is a friction measuring device designed to be towed behind a vehicle on a test surface (reference 9). The device consists of two test tires loaded vertically and "toed" out to include an angle of 15 degrees, thus forcing each tire to operate in a yawed-rolling condition with side forces directed away from and canceling each other. The device measures the tensile force in the axle and gives a measure of the surface friction being developed by the yawed test tires. The device can conduct tests on dry surfaces and is capable of using an on-board water tank to wet the test surface just ahead of the test tires.

Skid Trailer. The Florida Highway Department provided a test device which was used to help characterize the surface friction capability of some of the test surfaces used in the ITTV testing. The skid trailer and tow vehicle, shown in figure 8(b), consists of an instrumented trailer equipped with a water supply and dispensing system, and actuation controls in the tow vehicle cab for braking the trailer test wheel from a free-rolling condition to a momentary complete (100 percent slip) lockup (see reference 10). After the test apparatus is brought up to the desired test speed, e.g. 40 mph, water is dispensed at a constant rate to produce 0.04 in. surface water depth (delivered ahead of the test tire) and the braking system is actuated to lock the test tire. The resulting friction drag force acting between the test tire and the pavement together with the speed of the vehicle are recorded with the aid of suitable instrumentation. This skid trailer can also be operated on dry or naturally contaminated, e.g. rain-wet, surfaces.

British Pendulum Tester. This well-known device designed to provide a measure of surface microtexture was used in this investigation to help quantify the relative roughness of the texture for each of the surfaces tested. Microtexture is defined as a surface roughness quality on the sub-visible or microscopic level. The passenger tire industry uses such a parameter to help quantify long-term automobile and truck tire wear. Macrotexture, on the other hand, provides a measure of the surface roughness at a much larger scale. This is of the quality and scale one would perceive if one rubbed their hand on a surface.

The British Pendulum Tester (BPT) makes use of a pendulum to which is attached a rubber footpad (figure 9). The device is used by placing the feet of the tester on the surface

to be tested and leveling the apparatus. The footpad is then raised to a pre-determined height (angle) and released. The pendulum, and hence the footpad swing freely, allowing the rubber footpad to “scrape” the surface when the pendulum traverses through the vertical orientation. A certain amount of energy is then dissipated by friction and wear of the footpad. According to the theory of the device, the pendulum then swings upward to a height (angle) lower than the equivalent release point on the other side. This difference in height gives a measure of the dissipated energy and the relative surface microtexture. The height reading is in non-dimensional units; larger units denote a “rougher” surface which prevents the pendulum from rising to as high a point as compared to a smoother surface. Thus, the higher a reading, the “rougher” or higher a microtexture the surface is classified as having. Generally, on surfaces where one can “feel” an increased macrotexture, one would expect the BPT to indicate a higher microtexture as well. The BPT was used after wetting the surface to be tested. Some of the surfaces were not evaluated using the BPT but the ones that were tested were evaluated using the pendulum swing direction both parallel and perpendicular to the long axis of the runway. More information regarding the BPT can be found in reference 10.

Outflow Meter. The Outflow Meter is a device intended to provide a measure of surface macrotexture (reference 11). The meter consists of a rubber “doughnut” attached to the bottom of a tube open at its top end (figure 10). The doughnut is placed on the surface being evaluated and a standard quantity of water is poured into the top of the tube. Because the surface macrotexture does not allow the entire rubber doughnut to contact all the “valleys” in the surface texture, the water escapes through the contact patch and the time for the entire volume of water to escape is measured. The time then becomes

the relative measurement of surface texture using this device. Thus the shorter the time for the water to escape, the rougher the surface texture is defined.

Grease Sample Texture Measurement Kit. Another means of quantifying the macrotexture of a surface was included in this investigation. A grease sample texture measurement kit (figure 11) was used to find the average texture depth (ATD) of each of the surfaces tested in this study. The kit contains a supply of ordinary grease, a hard rubber squeegee, a plunger, and a short tube open on both ends with a handle. The short tube is filled with grease and provides a calibrated, known volume of grease for the measurement. The plunger is used to extrude the grease onto the surface being evaluated. The grease is evenly spread with the rubber squeegee as far as possible between two strips of masking tape placed at a known distance apart on the surface. At this point, essentially all of the “valleys” created by local “hills” on the test surface have been filled with the grease. The initial volume of grease is then divided by the measured area on the surface and yields a measure of the average depth of the surface texture or ATD. This parameter agrees well with the results one would feel while rubbing their hand on the surface. A more detailed discussion of the technique is given in references 9-12. One should note that there are other surface qualities that certainly must influence tire wear such as “sharpness” of surface disparities, but measurement techniques for these other qualities have not yet been fully devised or understood.

Computed Tomography. Computed tomography was used to provide an alternate means of defining tire rubber loss due to wear. A device, similar to medical CAT (Computerized Axial Tomography) scanners, passes x-rays through the cross-section of the tire and sensitive detectors are used to receive the attenuated signals on the opposite side

of the tire. By placing a calibrated block of known size in the scan with the tire, a digital measurement program can be used to measure the tire width or thickness before and after wear testing. An example of the tire profile dimensions before and after testing is shown in figure 12(a). In the figure, dimensions 1-40 represent scans parallel to the rotational plane of the tire thus providing 40 data points from the left towards the right shoulder of the tire to characterize the tire tread area wear. Figure 12(b) provides a representation of the tire cross-section before and after testing. The change in thickness can then be correlated with other measurements of tire wear. The advantage of this kind of examination is that many more “individual” or discrete measurements can be performed automatically in a non-destructive manner. More information on this technique can be found in reference 13.

Other Measurement Hardware. Several common measurement tools were also used in this investigation. To measure tire wear during the small aircraft tire testing using the ITTV, a sensitive scale was used which gave weight readings accurate to about one gram or 0.002 lbf. The entire test tire and wheel were weighed at various times during the tests on each candidate surface so that a history of tire rubber loss could be recorded.

For both the ITTV and the LSRA tests, a tire tread measurement gage was used to provide measurements of tire wear. The gage is designed to sit flat across the ribs of the tire tread and has an extendible probe which is pushed to the bottom of the tread grooves and measures tread depth remaining. For cases where Orbiter tire wear was expected to be between the bottom of the tread grooves and the first carcass cord layer, several small 1/4 inch diameter holes were bored into the main gear tire tread using a small rotary tool. These holes were bored 9/32 in.. deep until the first carcass cord layer was just exposed.

By measuring from the bottom of the hole to the outer surface of the tire, one could determine wear depth prior to exposure of the first carcass cord layer.

Texture Modification Devices

Four methods of modifying the existing concrete runway at the KSC SLF were employed in a number of ways to provide 16 new textures in addition to the existing two textures on the runway. The four methods were diamond blade grinding, Skidabrader™ shot-peening, rotopeening, and methacrylate coating. Table 1 presents a chart identifying the 18 texture test strips. Table 2 presents data for each of the 18 test surfaces including the results of Average Texture Depth (ATD) measurements, British Pendulum Tester (BPT) measurements, Outflow Meter measurements, and limited Mu-Meter and Skid Trailer testing. The Mu-Meter and Skid Trailer results are presented as non-dimensional values calculated by dividing the measured side loads by the vertical load on the test tires.

Although some surfaces were not evaluated with the BPT and the Outflow Meter as shown, these data can be used to quantitatively compare the different textures.

Figure 13 shows a sketch of the runway and where each test strip was located. Figure 13(a) shows an overall layout of each of the test areas used in this investigation. Figure 13(b) shows eight test strips used during the ITTV testing which are located towards the north end of the runway and east of the runway centerline. Figure 13(c) shows eight test strips used during the ITTV testing which are located towards the north end of the runway and west of the runway centerline. Figure 13(d) shows a sketch of the full-length test strips applied to the runway for LSRA testing. Note that Test Strips 1 and 3 had a different texture on the touchdown zones as compared to the center part of the strips, and that Test Strip 2 had the same texture application for the entire strip.

The primary, or original, surface type prior to modification is referred to either as TG, meaning the transversely-grooved 8000-foot-long section in the center of the runway, or as LG, meaning the longitudinally-grooved 3500-foot-long touchdown zones. These zones, often referred to as the corduroy touchdown zones, did not actually have grooving but rather the texture that remained after the 1988 grinding operation gave the appearance that longitudinal grooves had been installed as opposed to lateral grooving.

Diamond Blade Grinding. This texture modification technique uses a stack of diamond saw blades to cut into the existing texture. This technique has been used for many years to smooth sections of highways and recently has been used to alter the texture on some runways. Figure 14 shows one type of machine designed to grind concrete surfaces. The machine height can be controlled for depth of cut and water is typically used as a cooling agent. The slurry produced during cutting is typically vacuumed and pumped into holding tanks for later removal. The device is designed to traverse the surface slowly and forward speed is not normally varied. Figure 15 shows a close-up of a cutting head used on a smaller version of the machine shown in figure 16, and the spacers between blades can be adjusted so that a range of blades/inch configurations can be selected. For these tests, an ITTV test strip was cut (all ITTV test sections were 2-6 feet wide and 400 feet long unless otherwise noted) using a blade spacing of 5 blades/inch. For the LSRA testing, a 7 blades/inch configuration was used in a test strip 12 feet wide and 11500 feet long. This is the practical limit for normal blade spacing and provides a fairly smooth surface. Another ITTV test section was created using the same grinding machine but with a head using interlocking diamond saw blades which produced an extremely smooth surface similar to a polished stone surface. This same equipment was used to produce the

corduroy touchdown zones on the runway in 1988 using a blade spacing of 4 1/2 blades/inch. A photograph of this surface which is typical of this technique is shown in figure 17.

Skidabrader™ Shot Peening. The Skidabrader™ was used extensively to produce a variety of textures. This device, shown in figure 18, uses pressurized air to propel small steel shot at the surface being traversed. The intention is to break many of the sharp peaks on the original rough surface to reduce the ATD of the surface. The machine is also used to roughen smooth surfaces such as the rubber-contaminated touchdown zones of commercial runways. The steel shot also impacts other areas of the surface texture and one can imagine many possibilities of modification outcomes. The size and shape of the shot in addition to the shot velocity can be varied. The forward or traverse velocity of the machine can also be varied to dramatically change the resultant texture. The shot is vacuumed up after impact along with surface debris, separated and recycled to be used again. The machine produces a modified swath 6.5 feet wide. For the ITTV test strips, the Skidabrader™ was used with a single shot size, a single shot velocity, but with three different forward velocities. Six test strips were produced by traversing both the corduroy touchdown zone and the original center section of the runway at machine velocities of 100, 150, and 220 feet/minute. For the LSRA tests, one test strip 12-feet-wide was produced using the Skidabrader™ by traversing the full 15000-foot-length at 150 ft/min. in two swaths. Two other test strips were produced using the Skidabrader™ at the same velocity but only the 3500-foot-long corduroy touchdown zone on the end of the runway was modified as an entrance to a different texture strip in the center 8000 feet of the runway. For one case, the touchdown zone on each end of the runway was modified as an entrance for a texture described in the next section and for the other case only one end of the runway was modified (the LSRA test strip that was produced using the diamond saw grinding

technique). During the creation of all of the Skidabrader™ surfaces, many ATD measurements were taken and the operators of the equipment were required to produce a texture that varied in ATD by no more than 10% throughout the entire test section area.

Rotopeening. The rotopeener shown in figure 19(a) is a device with tungsten buttons attached to leather-like belts or straps. A head loaded with these straps of buttons rotates and as it does, the buttons “slap” the runway surface and cause the tops of the macrotexture peaks to be broken off much the same way as the Skidabrader™ does. The buttons were unable to penetrate the texture as deeply as the Skidabrader™ and thus had the most effect on changing texture on the very top surface of the runway and on the edges of the transverse grooves when applied in the center section of the runway (figure 19(b)). For the ITTV test strips, the buttons wore out occasionally and consequently the operators felt that different results would be obtained with old versus new belts. Therefore, on the corduroy touchdown zone of the runway, a test section using new belts was produced. This section could be compared with another path in the same zone using old belts. The operators suggested that the machine would produce a different result if it were operated in the transverse direction on the runway so a longitudinal strip produced by the machine operated in a lateral direction was placed in the center or transversely grooved section of the runway. For the LSRA tests, a 10-foot-wide laterally-rotopeened strip was placed in the center 8000-foot section of the runway with a 3500-foot-long Skidabrader™ strip as the entrance to this texture on each end of the runway. The machine only modified a 10-inch-wide swath at a time so this process was very time-consuming. Once again, operators of the rotopeening equipment were required to produce test sections which varied no more than 10% as measured by the ATD method.

Methacrylate Coating. The fourth method used to produce modified textures at the SLF involved the use of a low-viscosity liquid known as methacrylate (figure 20). This compound bonds to the concrete runway surface and dries extremely hard. The intention was to fill the low areas of the surface texture in hopes of reducing the ATD of the surface. A photograph of the surface would simply appear to be wet; the compound gave the impression of dried polyurethane. This liquid was applied (figure 20(a)) only on the corduroy touchdown zone texture because no efficient way to force it to stay on the “land” areas on the transversely grooved center section texture while it dried could be devised. One test strip was produced by using ordinary painting rollers to apply a single coat of the compound in a 2-foot-wide by 340-foot-long area. Another short test strip measuring 2 feet by 60 feet was produced by applying two coats of the compound. A close-up view of this coating after the liquid hardened is shown in figure 20(b). This strip showed that extra coats of this costly compound would continue to reduce the ATD but the strip was not long enough for wear testing.

TEST PROCEDURES

Instrumented Tire Test Vehicle Testing

The ITTV was used to measure and compare tire wear rates on a variety of short test strips modified using several techniques. A new 20 x 4.4 test tire was mounted on a standard aircraft wheel for each surface tested. The wheel was weighed without bearings prior to being installed on the test fixture axle mounted at the rear of the ITTV. This initial wheel

weight became the measurement standard for each test strip. To provide meaningful wear data for test strip comparisons, it was decided to attempt to conduct tests on each strip totaling about 4000 feet (in the case of one of the smoother surfaces, a total distance of over 7000 feet was achieved). In order to reasonably accelerate the wear rate of the test tires, the tires were always set at a fixed 8 degree yaw angle. To evenly distribute the expected wear across the test tire footprint, the test tire was yawed towards the opposite direction after every test run.

The ITTV was then driven to the desired test strip and lined up in preparation for a test. The data recording system on-board the ITTV would then be activated and the test tire would be lowered to the test strip surface and loaded to 4500 lb. The ITTV was then accelerated slowly up to approximately 25 miles per hour and driven in a straight line to ensure the test tire remained on the test strip. The ITTV would brake to a stop at the end of the test strip. The tire would be raised and the ITTV was then driven back to the original starting point for set-up to repeat the test to accumulate distance on the test tire.

The tire and wheel were removed after every two or three of the individual test lengths and taken to be weighed to provide a tire weight lost versus distance history. The tire tread depth gage was used each time the tire was weighed and tire tread depth measurements were recorded at 4 places around the tire circumference in each of the three grooves. The tire/wheel combination was then returned to the test axle and more distance on the tire would be accumulated in the same fashion. After wearing through the tire tread material, wear into the test tire carcass would commence. This changed the wear rate for those portions of the overall tests on each tire, but each tire was taken to a wear condition of approximately 5 cord layers thus preserving the capability to make wear rate comparisons

between surfaces. Data were periodically reviewed to ensure steady-state vertical and side loads were being maintained. The vertical load during each test reviewed was steady at the desired 4500 lb. All of the ITTV wear testing was conducted on dry test surfaces, and as a result, all of the recorded side loads regardless of the test surface were approximately 1700 lb throughout each test. A total of 168 individual tests were conducted on the ITTV test strips to provide wear rate comparison data.

For wet friction evaluation of the modified surfaces, the ITTV was used for 20 tire cornering tests at yaw angles of 2, 4, and 8 degrees under both wet and dry conditions at a 4500 lb vertical load condition. The surfaces included in this testing were the single coating of methacrylate strip (test strip 2), the Skidabrader™ 150 ft/min. strips on both the corduroy touchdown zone and the center section (test strips 5 and 6), the solid head cutter diamond grinding on both the corduroy touchdown zone and the center section (test strips 14 and 15), and both the unmodified corduroy touchdown zone and the center section (test strips 17 and 18). Only these test strips were evaluated for wet friction because it became clear that the other textures would not be selected as full-scale test strip candidates. The solid head cutter diamond grinding test strips had excellent wear characteristics as will be shown but were unlikely to have satisfactory wet friction performance.

For these tests, the ITTV was driven over the desired test strip both at walking speed and at 60 miles per hour. For the high speed tests, the test tire would be lowered just as the ITTV was entering the test section, which typically consisted of a 40-foot length of dry surface of the desired type followed by a 40-foot length of the same surface texture which had been wetted by a KSC fire truck just prior to the test. The water condition simulated the conditions shortly after a typical rain shower, with a water depth of approximately 0.02-

0.04 inches. The same data were recorded as for the wear testing except for tire weight loss data which was not considered relevant to these friction tests.

Landing Systems Research Aircraft Testing

A total of 23 flight tests were conducted using the LSRA to impose full-scale landing conditions on Orbiter main gear tires. The flight tests covered a wide range of conditions that might be experienced during actual flight operations and included simulating a variety of piloting techniques which might affect tire wear. Since the intent of the tests was to expand the crosswind landing envelope to 20 kts, all of the tests were conducted simulating a 20-kt crosswind from either the right or the left. The test aircraft was determined through previous testing to be a reliable and repeatable facility to perform the full-scale testing; high-confidence in the system to perform the test programmed into the control computer had been achieved. The challenge for the test team was to program the correct types of tests to make the decision-making process as clear as possible. To simulate 20-kt crosswind landings, time histories of tire vertical load, tire yaw angle, and speed are needed. A tire cornering model based upon tire vertical load and yaw angle (by far the two most important parameters which influence tire cornering) was previously developed using ALDF and LSRA test results. This tire cornering model produces tire side force as its output and this force was used as one of the inputs into a Shuttle Orbiter landing and rollout simulator program. Other important parameters such as vehicle control surface dynamics and vehicle aerodynamics were also modeled in the simulator. Based on aerodynamic inputs modeling a 20-kt crosswind on the vehicle during landing, the

simulator output included main gear tire yaw angle time histories. These time histories were checked by conducting tests with the LSRA using the same time histories and measuring tire side forces. The side forces closely matched the side forces predicted by the simulator thus providing a check of the modeling process. This provided confidence that the LSRA could actually simulate crosswind landings on the test tires.

Test Conditions. A number of 20-kt crosswind landing profiles were developed in order to define a range of possible conditions the Orbiter tires might be subjected to in actual flight experience (Table 3). The most important parameter relative to Orbiter main gear tire wear was yaw angle. The yaw time history for the tires has a nominal value for each crosswind and Orbiter speed during the rollout but other flight disturbances add to or subtract from that baseline. For example, if the Orbiter lands with a lateral drift rate at touchdown, the touchdown yaw angle could go up or down depending on the direction of drift. If the pilot allows the crosswind to push the vehicle downwind prior to derotation then a steering maneuver to bring the vehicle back to the centerline will cause increased yaw angle and therefore increased wear on the tires. Derotation speed and rate also affects main gear tire vertical loads which ultimately will manifest themselves as changes in the tire wear behavior. Although there are many possible flight conditions, three types of 20-kt crosswind profiles were generated and they are referred to as either “Case 9”, “Case 10”, or “Case 11” in Table 3. All three cases assumed a touchdown speed dispersion of 20 kts which forced a 225-kt touchdown speed for the tires. It should be noted that figure 5 is a graphical representation of case 9. The main difference between case 9 and case 10 is the addition of the triangular steering pulse just after peak tire load. Peak tire load on the main gear tires occurs just as the nose tires touchdown after the derotation maneuver for the Orbiter. The steering pulse is intended to model a 20 foot “S” type maneuver an aggressive pilot would perform after having been pushed downwind by a strong

crosswind. This maneuver had been performed several times in actual Orbiter flight experience even though such a maneuver was discussed and discouraged during pilot training.

Case 11 is similar to case 10 except that the crosswind is modeled as coming from the left as opposed to the right (as in cases 9 and 10). The yaw angle time histories for cases 10 and 11 are different; the Orbiter main gear tire has a phenomenon known as ply-steer which produces an uncommanded side force to the left as it rolls even at zero yaw angle. To achieve the same side force to combat identical aerodynamic side forces, the vehicle assumes a slightly lower yaw angle during rollout with crosswinds from the left because of the “free” forces developed by the four main gear tires. This phenomenon cannot be mitigated by mounting tires backwards on the wheels or by rolling the tires backwards. Due to the unavoidable asymmetric nature of the composite structure of the bias-ply tire design, the ply-steer force always acts in a single direction. The rollout simulation program had a small anomaly that resulted in a 0.2 degree increase in anticipated yaw angle at the time of peak load which was simply accepted in these flight tests.

These three cases therefore include a number of dispersions from the expected norms for a crosswind landing but represent the types of events that could be encountered in actual flight. These dispersions could be added together in a Root-Sum-Squared (RSS) manner resulting in a more benign set of speed, load, and yaw angle time histories, but it was decided that these dispersions were independent and the problems were likely to cascade under high-crosswind conditions. Therefore the dispersions were linearly combined to define a worst-case landing profile. The test tire would thus have to survive the worst of these profiles to verify a 20-kt crosswind capability.

Landing Systems Research Aircraft Procedures. For each flight using the LSRA, a new test tire was installed on the aircraft test fixture and inflated to 340 psi at

ambient conditions. The aircraft normally conducted a “preroll” on the test tire in which the tire was loaded to about 60000 lbs and rolled 10000 ft with zero yaw angle. This preroll was designed to heat up and work the nylon carcass cords to precondition the carcass in case the tire’s first landing (in Orbiter use) was an RTLS abort. The technique helps to insure tire survivability under those conditions. Although this was not a concern during the LSRA testing, it was desirable to treat each test tire as if it were a flight tire on the Orbiter. After the preroll, the aircraft was either parked overnight to allow the test tire to cool back down to ambient temperatures (the test tire temperature would normally climb over 140 deg F during the preroll) or the tire was sprayed for approximately 45 minutes with cool water to reduce the temperature to about 90-95 deg F.

For a typical test run, the aircraft would make a normal takeoff with the test tire retracted, fly a closed loop around the SLF, and set up for a test landing by aligning the aircraft with the desired 10-12 foot wide test strip. Most of the tests required a test tire touchdown speed of 225 kts which required the LSRA test pilot to land the vehicle 5 kts faster. After LSRA touchdown, the pilot would derotate the aircraft and at the proper speed would give a “start test” command. The test conductor on-board the aircraft then enabled the test control computer to perform the test as programmed. The pilot steered the aircraft to keep the test tire on the test strip (for all tests, the test pilot never once strayed out of the 10-12 foot wide test strips) and decelerated the LSRA to match the desired speed profile simulating the rollout and stop of the Orbiter. The test conductor monitored the test to insure the control computer was following the desired profiles. A video operator was responsible for observing the LSRA landing gear and the test tire, and for monitoring aircraft fire suppression systems should they be needed.

Since these tests were known to be near the maximum wear capability of the tire, the crew was constantly aware of the test progress. If the test tire failed due to excessive wear

(which it did several times), the crew executed procedures to retract the test tire and, depending on the speed and position of the LSRA, would perform either a takeoff or bring the aircraft to an emergency stop.

The results of a test tire failure with personnel near it would be catastrophic due to the tremendous potential energy stored in the tire. After a test, the test tire wear condition was evaluated using the on-board video coverage. If the tire remained inflated but had worn into 8 or more of its 16 cord layers (the tire would normally fail if wear progressed into layer 9 or 10) the aircraft was parked and a robotic device was used to approach the test tire and drill a hole into the tire sidewall using an ordinary cordless drill thus deflating it. If wear was not severe, the tire and wheel assembly was allowed to cool for an hour and then dismounted from the aircraft and removed from the test axle.

LSRA touchdown positions as well as the touchdown position of the test tire itself were marked and measured on the SLF runway surface by ground observers. Rollout lengths were measured and recorded. Comparisons of the desired-versus-actual time histories of the test parameters were produced almost in real-time during the test so decisions about the next scheduled test could be made quickly.

The LSRA was also used to conduct limited wet-runway tests. For these tests, the control computer was normally programmed to load the Orbiter test tire to 75, 100, 150, and 200% of its rated load and yaw the tire in a stair-step fashion at each load. The tire was yawed rapidly and then held at the desired yaw angle (normally +/- 1, 2, 4, and 7 degrees) for a short period to let the side force stabilize at each steady yaw angle. Such tests were conducted at speeds ranging from 50 to 200 kts. Due to limited resources and time during the LSRA testing, wet friction tests were conducted on the "smoothest" version of the full-scale test strips. In the touchdown zones, the wet tests were conducted on the Skidabrader™ surface as it was assumed it would display the highest friction loss of the

two possible touchdown zone modifications. In the center section of the runway, wet tests were conducted on the rotopeened test strip since that strip had the “smoothest” feel and also was assumed to lose more friction capability when wet as compared to the other two textures in the runway center section. The intent of the tests was to demonstrate satisfactory wet friction characteristics even on the “worst” surfaces so that the friction loss on the rougher surfaces due to wetness (increased roughness almost always provides more protection against friction loss due to wetness) could be ignored as a disqualifying factor for selection of those textures as potential solutions to the wear problem. The runway was wetted just prior to a LSRA landing for each test using a water tank truck. The tank truck was driven at approximately 30 miles per hour next to the intended test strip allowing water to drain from a 4” valve and wet the lateral half of the test strip closest to the runway centerline. The runway crown in that area (1%) caused the other lateral half of the strip to be wet prior to LSRA testing which would usually occur within about 3-4 minutes. The wetness condition was approximately the same as for the ITTV wet friction tests.

DATA REDUCTION

Instrumented Tire test Vehicle Wear Tests

Data collected for the ITTV wear testing consisted of recording the distance traveled during each test (normally 400 feet), the weight loss due to tire wear after approximately every second test, and recording of various environmental data for later analysis if necessary. The tire weight loss was measured in grams but will be presented in this report as lbm to provide easy-to-understand data when plotted. Wear rates in lbm/ft will be presented as the slope of the last measured weight for each test tire.

Instrumented Tire test Vehicle Wet Friction Tests

Data collected during the ITTV wet friction testing consisted of test tire yaw angle, vertical load, and side force. The side force friction coefficient for each test, μ , was calculated by dividing the average steady side force produced by the test tire by the average vertical load on the test tire during each test. The μ values for the 2, 4, and 8 degree tests on each wet surface were compared to the μ values for a dry concrete surface at the same yaw angles. For each surface and yaw angle, the wet μ value was divided by the dry μ value to give a percentage of the average dry value. The three values of the percentage of average dry values for each surface were then averaged to give a single value for each surface when wet. This was done for both speed conditions.

Landing Systems Research Aircraft Wear Tests

Data collected during the LSRA wear testing included test tire yaw angle, vertical load, side load, tread temperature, vehicle speed, and video coverage of the tread area of the tire. These parameters were the most important in terms of quantifying Orbiter main gear tire wear, however, a wealth of other information was collected. Other instrumentation was used to define, control, and track many support functions on the aircraft which allowed the testing to be conducted. The side loads produced by the tire as a result of rolling under various combinations of vertical load and yaw angle, are critically important in the wear phenomenon.

A parameter known as side energy was previously developed (reference 4) in which tire wear can be expressed as a function of the work which the tire performs in the lateral direction during cornering. The side energy can be calculated as:

$$E = \int_0^T F_s (\sin \psi) V dt \quad (1)$$

where

E = Side energy

F_s = side force

ψ = yaw angle

V = velocity

t = time

T = duration

The work term defined by the equation can be thought of as a force acting through a distance; the work is the integrated product of the side force and the lateral component of the longitudinal distance traveled. This work, or energy, term has been used with success in providing a tool for predicting tire wear under different combinations of speed, load, and yaw angle on a given surface. Note that it appears that the technique might allow prediction of wear due to braking since that also can be thought of as a force acting through a distance. However, one must be careful when applying the phenomenon to braking because during braking, most of the energy is absorbed by the brake, whereas for cornering all of the energy is being absorbed by the tire.

Using the LSRA on-board recorded data, time histories of side force, yaw angle, and speed were used according to the above equation to provide a time history of the side energy for the test tire. Then the videotape of the test as seen from the front of the test tire was reviewed and the time at which different carcass cord layers became visible was recorded to be correlated with the side energy time history. As the first and successive cord layers

of the test tire carcass become visible due to wear, a “bullseye” pattern is produced which makes the interpretation of tire wear reasonably easy. Figure 21 shows a photograph of a typical bullseye pattern. As stated earlier, other data were analyzed during these tests but the wear data became the most important on which to base a runway modification decision.

Landing Systems Research Aircraft Wet Friction Tests

Data relied upon for these tests were the same as for the wet ITTV tests. A single yaw angle of four degrees was used during these tests. The side forces obtained during these tests were compared to the side force obtained on dry concrete (which could be accurately predicted by the cornering model) at four degrees and at the different vertical loads tested. The side forces for the wet tests were then divided by the dry side force values to yield a wet behavior for the different surfaces tested expressed as a percentage of the dry friction value. This was done to allow wet runways to be easily modeled in Orbiter rollout simulators. A wet runway can usually be satisfactorily modeled by multiplying dry friction by a percentage and dividing by a velocity term which reduces friction values even further as speed increases.

RESULTS AND DISCUSSION

It should be noted that certain testing was conducted using both the Mu Meter and the Skid Trailer to help characterize the wet friction performance of the ITTV test strips. Those data were helpful in understanding how different techniques for measuring surface friction relate to each other and provided background information as to the kinds of tests that can be conducted. Also note that texture measurements made using the British Pendulum Tester and the Outflow Meter provide background information as to the various methods

developed to quantify surface texture. Data generated by these four devices, however, were not used in the decision-making process for selection of full-scale test strips on which LSRA tests were conducted and are thus not discussed in this section.

Instrumented Tire test Vehicle Wear Tests

Each of the modifications applied to the KSC SLF runway used a technique which was sensitive to the original texture of the surface. For example, the Skidabrader™ was used to smooth each of the original textures on the runway, but the device was also used elsewhere to *roughen* the surface. Therefore, each of the two original textures on the runway surface were treated as different runways, allowing for the possibility that the technique chosen to modify the touchdown zones might not be the same technique chosen for modifying the center section.

Average values of test tire wear rate for each surface type are presented in Table 4. Figure 22 presents a plot of test tire wear as a function of distance (at an 8-degree yaw angle) for the 20 x 4.4 test tires on modifications applied to the corduroy touchdown zone texture. The figure shows that the original corduroy surface produces the highest wear rate. These data suggested that any reasonable attempt at “smoothing” the surface would result in better tire wear performance. The figure shows that the 5 blades/inch diamond grinding technique improves the wear performance of the surface but not to the same degree as some of the other techniques. This was expected because the original surface was created using exactly the same technique but with a slightly wider, or rougher, blade spacing of 4 1/2 blades/inch.

Two modification techniques provided extremely similar tire wear behavior, including the Skidabrader™ at both 100 and 150 ft/min. and the rotopeener (with a new belt). These two methods of modifying the surface produced a noticeably different “feel” to the touch but had extremely similar ATD’s (0.0104-0.0115 in.). This suggests that there may be a strong link between surface wear characteristics and ATD. The remaining data plotted in figure 22 shows the wear behavior of the test tire on the original corduroy touchdown zone surface treated with a single coat of methacrylate. The plot shows that the methacrylate produced the least tire wear rate of any tested on the touchdown zone textures.

Figure 23 presents a plot confirming this strong link and shows the wear rate for the test tires on both the transversely-grooved center section and the corduroy touchdown zone with their respective modifications plotted as a function of ATD. The figure, however, does not completely explain the wear phenomenon. As seen in Table 2, the ATD for the 5 blades/inch diamond grinding applied to the corduroy touchdown zone is 0.0108 in. This is virtually identical to the values for the Skidabrader™ and rotopeening techniques, yet the wear on that surface was worse. This provides evidence that there must be other parameters such as sharpness qualities that the ATD technique does not measure but are important nevertheless. The values in Table 2 for the BPT of these surfaces also show that the BPT cannot discern a significant difference among these four surfaces. Table 2 shows the surface with the single coating of methacrylate had an ATD of 0.0123 in. This apparently small change in the ATD as compared to the Skidabrader™ and rotopeened surfaces (including the fact that it reflects an even “rougher” surface) is further evidence of the existence of other unmeasured parameters. Although equivalent side loads were produced during tests on all these surfaces, one could hear an unusual noise as the test tire

traversed the methacrylate test strip. The low-pitched sound gave one the impression that the tire was “slipping” on this test surface more than on the other test surfaces.

The similar wear behavior measured on the 100 and 150 ft/min. Skidabrader™ test strips combined with the data in Table 2 showing similar ATD values for them as well as the 220 ft/min. Skidabrader™ test strip led the test team to decide that no advantage was likely to be gained by conducting tests on the 220 ft/min. Skidabrader™ test surfaces either on the original corduroy touchdown zone or the original center section. Likewise, very little difference in the ATD was measured for the various techniques of using the rotopeener (new-vs-old belts or longitudinal-vs-lateral installation) so only the one application for the rotopeener applied to the corduroy touchdown zone was tested. The number of available test tires was such that some narrowing-down of possibilities was necessary in real-time during the testing.

The test strip produced by the solid head cutter diamond grinding was exceedingly smooth (Table 2); the test team was convinced that the wear tests on that surface would have shown the lowest tire wear values of any of the test surfaces. Since this surface was smoother than other ungrooved runway surfaces that are known to have unacceptable wet friction characteristics, it was felt that the surface would not meet the wet friction criteria later in the testing and thus wear tests were not performed on this surface. The results of this phase of testing indicated that the anticipated reduction of tire wear to one-half of the original value was possible on the corduroy touchdown zone and that at least three of the proposed methods could accomplish that goal; the Skidabrader™, rotopeening, and a single coating of methacrylate.

The results of the 20 x 4.4 tire wear testing on the original or transversely-grooved center section are plotted in figure 24 which shows test tire wear as a function of distance. Again, tests on the original surface were conducted to define the baseline wear behavior to be improved upon. Data were collected on the test strips in the original center section which had been modified by the Skidabrader™ at both 100 and 150 ft/min. The results showed that forward speed of that device did not have a significant effect on ATD or tire wear (figures 22 and 24) and therefore the decision was made to refrain from further testing on the strip produced by the Skidabrader™ at 220 ft/min.

Data collected on the test strip modified using the rotopeener longitudinally showed results similar to those experienced on the corduroy touchdown zone wherein the longitudinally-rotopeened surface produced the same wear as the Skidabrader™ surfaces. The laterally-rotopeened test strip in the original center section produced significantly lower tire wear than the Skidabrader™ surfaces as seen in figure 24. Even though the data in Table 4 show nearly identical ATD's for the laterally- versus the longitudinally-rotopeened surface, the tire wear was significantly lower for the lateral case. The laterally-rotopeened surface did have a noticeably smoother "feel" as compared to the longitudinally-rotopeened surface, again implying there are other unknown qualities which influence tire wear.

In figure 24, the lowest-wear surface is the one produced using the solid head cutter diamond grinding technique. Although this surface would have surely been too slick (when wet) for the corduroy touchdown zone tests, it had some merit as a modification technique in the original center section because transverse grooves remain after the technique has been applied. It is known that providing an escape path for water in the tire footprint reduces the severity of the friction versus speed penalty for wet surfaces. Tests

on that surface showed it reduced the tire wear rate to one-third of the wear rate for the original center section, exceeding the 50 percent reduction deemed necessary to achieve a 20-kt crosswind Orbiter landing capability. Thus it appeared that two techniques had the capability to reduce tire wear in the original center section to acceptable levels; the solid head cutter diamond grinder and lateral rotopeening.

Note in Table 4 that the wear rate for the original center section and the corduroy touchdown zone are nearly identical as are their ATD's. This result suggests that for rollout conditions (countering crosswinds and steering as opposed to spin-up) the transverse grooves in the center section do not cause increased tire wear. However, the grooves are shown to be one of the primary tire wear factors during the spin-up process (reference 2).

Instrumented Tire Test Vehicle Wet Friction Tests

As mentioned earlier, the wet friction performance of a surface usually decreases with increasing speed and with reductions in surface roughness. The Orbiter rollout simulator has shown that a 50% decrease in wet friction performance of a runway can be accepted, since vehicle control is achieved not only by using tire forces but by using aerodynamic forces generated by control surfaces as well. Figure 25 presents the result of extremely limited testing of some of the candidate strips using the ITTV. The figure shows the percentage of dry cornering values obtained on the wet test strips as a function of speed.

Although the ITTV test speed of 50 kts does not adequately permit the prediction of surface performance at 200 kts, the data were used to provide some insight into general friction trends. The data show the original two surface textures (the original center section

and the corduroy touchdown zone) retain the highest level of wet performance at slow speed. The 150 ft/min. Skidabrader™ surface on both of the original surfaces showed good retention of friction at low speed. The solid head cutter diamond grinding test strip and the single coat methacrylate test strips displayed more performance loss at slow speed than the other surfaces which was expected due to their smooth nature. The methacrylate strip was not tested at the maximum ITTV speed because it was assumed it would lose too much performance at high speed. The solid head cutter diamond grinding technique applied to the original center section was tested at about 50 kts and showed what appeared to be a gain in performance as compared to its slow speed value. Based on what is known about wet surface friction behavior, such gains are not likely to consistently occur and thus this provides an indication of the level of accuracy of this type of testing. The 150 ft/min. Skidabrader™ surfaces on both original textures were tested at about 50 kts. The data show very little performance loss for the technique as applied in the center section, but a relatively large loss of about 15% of the dry performance for the technique as applied on the corduroy touchdown zone. This trend, if it continued linearly up to 200 kts, would suggest that too much performance loss would occur for a Skidabrader™ modification of the corduroy touchdown zone. However, since the Orbiter has a wealth of aerodynamic control in the early phase of landing (due to speed) when it is traversing the touchdown zone, the need for high friction in that zone is somewhat diminished.

Landing Systems Research Aircraft Wear Tests

Time and cost were two important considerations in determining what modification techniques should be applied in full-scale test strips for LSRA testing. The methacrylate treatment is a very costly one, and concerns arose regarding the uniqueness of it. No other runway experiences had been gained using that treatment, and there was a reluctance to

have the KSC SLF be the test case for this technology. The application cost for the Skidabrader™ device was about \$1.00 /square yard, and the cost for rotopeening was about \$1.20 /square yard making both treatments very economical. The application rate, and therefore time, for the treatments were quite different. The Skidabrader™ travels at 150 ft/min. and modified a swath 78 inches wide which provides an application rate of about 108 square yards/min. The rotopeener device is controlled manually, travels at 50 ft/min. and modifies a swath just over 10 inches wide, providing an application rate of about 5 square yards/min.

Based on the wear behavior of the test surfaces measured using the ITTV, the limited wet friction performance measurements, and cost and schedule requirements, a recommendation was offered and accepted to initially apply two full-scale test strips near the KSC SLF runway centerline for LSRA full-scale Orbiter tire testing. Sketches of these test strips are shown in figure 13(d) and are denoted as Test Strips 1 and 2. As described previously, Test Strip 1 (West Strip) consisted of an 8000-foot-long center section modified with the rotopeener used in a lateral direction with a 3500 foot long entrance on each end produced with the Skidabrader™ at 150 ft/min. Test Strip 2 (East Strip) was produced using the Skidabrader™ at 150 ft/min.

Figure 26 shows a plot of the wear performance of the Orbiter tires on the original surface prior to any modification. The plot shows tire wear as a function of side energy (eq. 1). Tire wear is shown both in cord layers and inches with the first cord layer the closest one to the tire tread. As shown in figure 7, about 9/32 in.. of wear is required to expose the first cord layer. The Orbiter tire has been extensively tested, and a wear limit of six cords (of the available 16) has been established as a safe wear condition for the tires at the end of a rollout. The band denoting the existing KSC runway represents the range of experience of

tire wear on that surface, as tire wear variability can be as high as several cord layers at equivalent energies. The two vertical bands represent the energy the tire may be required to absorb for both a 15- and 20-kt crosswind landing. The bandwidth represents the reasonable range of energy that may be experienced in each crosswind condition depending on pilot performance and atmospheric uncertainties. The lower energy level of each band shows the energy required during a “perfect” landing where no anomalies are experienced and no steering other than that necessary to just counter the steady crosswind is performed. The 20-kt crosswind band shows that approximately twice as much energy is required to be absorbed by the tire than for the 15-kt crosswind case.

Figure 27 shows a bar chart of various dispersions shown in Table 3 that increase the energy requirement of the tires. The right edge of the bands in figure 26 represent the energy requirements when all dispersions are present (at 20-kt crosswind). It should be noted that these studies were conducted assuming steady crosswinds and actual flight rules use maximum winds including gusts so that a 20-kt steady crosswind capability as measured during these tests includes some margin in capability as compared to a real flight where steady winds are almost never encountered.

The data in figure 26 indicate that the unmodified surface is unable to support even a 15-kt crosswind if significant dispersions are present. To verify this observation, note that a vertical line at the right edge of the 15-kt band will intersect the lower curve at about 3 cords of wear and will intersect the upper curve at about 9 cords of wear. Prudent judgment would lead to the conclusion that it is likely that the defined safe limit of 6 cords will be exceeded. Testing has also shown that the tire usually fails in the 9-10 cord region of wear. Thus a tire failure under 15-kt crosswind conditions is a possibility that must be

considered. Figure 26 also shows a band denoting the side energy associated with the runway as modified by the Skidabrader™. The improvement resulting from this technique is quite evident. A 15-kt crosswind landing can easily be accommodated. A 20-kt crosswind landing capability is feasible except for the most severe conditions, and even then the likelihood of actual tire failure is low. These results were encouraging and suggested the benefit of further studies of the Skidabrader™ modification technique.

Figure 28 shows the result of a number of tests conducted on two full-scale test strips shown in figure 13(d) (Test Strips 1 and 2). The figure shows tire wear as a function of side energy with tire wear scaled in both inches and cord layers. The upper shaded region shows tire wear behavior on the original surface under high landing speed and high crosswind conditions. The lower shaded region shows tire wear behavior at more benign landing conditions including touchdown speeds up to 200 kts and crosswinds lower than 15 kts. The legend shows each run as having been conducted under either Case 9, Case 10, or Case 11 conditions from Table 3. A LSRA “calibration” run is shown as the open square data symbols in figure 28. This run was used to verify that the LSRA could produce repeatable wear results before examining the modified surfaces. The data points represent the energy levels retrieved from the flight data at the point in time each cord layer became visible on the time-correlated flight videotape. Connecting the data points shows the progression of tire wear as side energy was accumulated by the tire. The data for both test strips show that a significant reduction in tire wear is achieved by smoothing the original textures. The data indicate that the tire wear on Test Strip 2 was slightly less than for Test Strip 1. This seems contrary to the idea that less wear would be observed on the surface that was “smoother” which in this case was Test Strip 1 (the strip with the rotopeened center section). The ATD for Test Strip 1 was 0.008 inches while the ATD for

test Strip 2 was 0.010 inches. In addition, Test Strip 1 was noticeably smoother to the touch than Test Strip 2.

When observing the tire damage after each of the tests, it appeared that more discoloration and tread delamination occurred during the testing on Test Strip 1 than during the testing on Test Strip 2. These findings are indicative of higher tread temperatures on the Test Strip 1 tires. Subsequent analysis of the tread temperature data for those flights confirmed slightly higher average tread temperatures were present. The higher temperature causes parts of the tread rubber to revert back near their uncured state and to lose adhesion to the textile carcass. These delaminations cannot support the high shear loads during cornering thus ripping off and exposing the carcass to the runway and causing more overall damage to the tire. It was surmised that the higher temperatures were due to the increased smoothness of Test Strip 1 itself. By causing less initial tire wear due to the smoothness of the surface, the tire must retain more of the hysterical heat created by yawed rolling and deflection due to vertical load. The rubber that would have carried away some of the heat as it is worn away on a rougher runway surface is now retained and causes the heat damage described above.

To evaluate this theory, Test Strip 3 (Far West strip shown in figure 13(d)) was installed on the runway. This test strip used the Skidabrader™ texture in the corduroy touchdown zone as an entrance to the new center section texture created by using a diamond blade grinding technique with a 7 blades/inch spacing. Test Strip 3 had an ATD of 0.003 inches and was intended to represent the smoothest test strip that could be installed quickly and inexpensively. Since the ATD was so low, it was hoped a clear change in the wear behavior of the tire would be observed. Figure 29 shows the wear results for Test Strip 3.

(Results from figure 28 are repeated in this figure but in lighter shade so that the results of testing on Test Strip 3 can be easily discerned. The energy bands associated with 15- and 20- kt crosswinds are also shown.) The figure shows that the texture in Test Strip 3 did not result in a clear decrease of tire wear as compared to the results on Test Strips 1 or 2. Instead, Test Strip 3 sometimes showed more wear and sometimes less wear than on Test Strip 2. Subsequent testing using the LSRA on the smooth, ungrooved runway at Edwards Air Force Base, CA confirmed these results. Nevertheless, the results of the LSRA wear testing at the KSC SLF showed that using the Skidabrader™ at a nominal 150 ft/min. rate on both the corduroy touchdown zone and the original center section produced a surface that appeared capable of increasing the Orbiter tire crosswind landing capability to 20 kts (figure 26).

Landing Systems Research Aircraft Wet Friction Tests

The LSRA was used to conduct tests on the full-scale test strips to provide assurance that sufficient wet friction capability would be retained for Orbiter directional control and braking. Due to limited time and test resources, only two sets of tests were conducted. The first set was conducted on the rotopeened center section of Test Strip 1 prior to the conclusion of the wear studies and thus before it was known the modification recommendation would be to use the Skidabrader™. The results of these tests are presented in figure 30. The plots show the percentage of dry friction retained when operating at different speeds on the test surfaces. The data in the upper curve show that the rotopeened center section retains virtually all of its dry capability even when wet. This result is due largely to the retention of the transverse grooves in the test strip. This result provides confidence that the “rougher” Test Strip 2 produced using the Skidabrader™ would also have satisfactory wet friction performance under full-scale conditions.

The middle curve for tests conducted on the corduroy touchdown zone modified using the Skidabrader™ shows the same trend identified by the ITTV test on that surface in which a decrease in friction level as speed is increased is observed. The tests using the LSRA at low speed corroborate the results obtained by the ITTV at its maximum speed. The data show that the friction on the Skidabrader™ surface applied to the touchdown zone decreases to about 40% of the dry value at approximately 200 kts. This was deemed to be acceptable and was significantly better than the wet Edwards runway surface behavior as shown in the lower curve. For the wet Edwards runway, the friction level drops to only 25% of the dry value when operating at 200 kts. This severe reduction in friction levels was reported to be unacceptable, and any runway modification would have to perform better than the Edwards wet runway.

Final Recommendation

Based on the ITTV wear testing, the ITTV wet friction testing, the LSRA wear testing, and the LSRA wet friction testing, a recommendation was made to and accepted by the Shuttle Program Office to modify the entire KSC SLF runway using the Skidabrader™ operated at 150 ft/min. The runway modification was performed in September, 1994 (see aerial view in figure 31), and numerous Orbiter landings have been performed on it at crosswinds as high as 12 kts, to date, with wear results as predicted by the curves shown in figure 26. The STS program will continue to monitor tire wear as a function of side energy as opportunities to land in higher crosswinds arise. Providing the tire wear capability for 20-kt crosswind landings will permit the program to realize an increase in the statistical

probability of meeting short launch window opportunities, and will provide increased safety margin for normal end-of-mission landings under crosswind conditions.

CONCLUDING REMARKS

An experimental investigation was performed to define a texture modification for the existing KSC SLF runway which would provide an increase in Orbiter main gear tire wear capability sufficient to support Orbiter landings in crosswinds as high as 20 kts. Tests were conducted using an instrumented vehicle to compare the friction and wear characteristics, at small scale, of a number of proposed texture modifications placed into the SLF runway surface itself. A strong link between ATD and tire wear was observed. Based on these tests, three candidate surfaces were chosen to be tested at full-scale using a highly modified and instrumented transport aircraft capable of duplicating full Orbiter landing profiles. Test strips for the three candidates were prepared for the entire length of the 15000 foot-long runway.

The full-scale Orbiter tire testing revealed that tire wear could be reduced approximately in half using either of two treatments. Full-scale testing also revealed a phenomenon which caused increased tire damage when operating on a runway smooth enough to prevent sufficient wear to carry away excess tire heat. For a given tire, it appeared that a balance between surface texture and tread heating can be achieved to minimize tire wear or damage. A device known as the Skidabrader™ was shown to be effective at reducing the texture of the existing KSC SLF runway while retaining adequate wet friction performance. The reduced texture approximately doubled the capability of the tire to absorb side energy thus providing the ability of the tire to withstand 20-kt crosswind landings while retaining some wear margin to allow for various landing dispersions. The Skidabrader™ was used to

modify the entire KSC SLF runway. Since completion in September, 1994 numerous landings have been conducted to date with no tire wear anomalies. The runway surface texture will continue to be monitored as will Orbiter tire wear behavior in the future, as opportunities to land in higher crosswinds arise.

References

1. Daugherty, Robert H.; and Stubbs, Sandy M.: *Spin-up Studies of the Space Shuttle Orbiter Main Gear Tires*. SAE paper 881360, Aerospace Technology Conference and Exposition, Anaheim, CA Oct. 1988.
2. Daugherty, Robert H.; and Stubbs, Sandy M.: *The Effect of Runway Surface and Braking on Shuttle Orbiter Main Gear Tire Wear*. SAE paper 922038, Aerospace Technology Conference and Exposition, Anaheim, CA Oct. 1992.
3. Daugherty, Robert H.; Yager, Thomas J.; and Stubbs, Sandy M.: *Shuttle Landing Runway Modification to Improve Tire Spin-up Wear Performance*. SAE paper 881402, Aerospace Technology Conference and Exposition, Anaheim, CA, Oct 1988.
4. Daugherty, Robert H.; and Stubbs, Sandy M.: *Cornering and Wear Behavior of the Space Shuttle Orbiter Main Gear Tire*. SAE paper 871867, Aerospace Technology Conference and Exposition, Long Beach, CA, Oct. 1987.
5. Byrdsong, Thomas A.; McCarty, John Locke; and Yager, Thomas J.: *Investigation of Aircraft Tire Damage Resulting From Touchdown on Grooved Runway Surfaces*. NASA TN D-6690, March 1972.
6. Yager, Thomas J.; and Horne, Walter B.: *Friction Evaluation of Unpaved, Gypsum-Surface Runways at Northrop Strip, White Sands Missile Range, in Support of Space*

- Shuttle Orbiter Landing and Retrieval Operations*. NASA Technical Memorandum 81811, June 1980.
7. Yager, Thomas J.: *The Aircraft Tire Wear Problem*. SAE paper 951391, Aerospace Atlantic Conference, Dayton, OH, May 1995.
 8. Carter, John F.; Nagy, Christopher J.: *The NASA Landing Gear Test Airplane*. NASA TM 4703, June, 1995
 9. Yager, Thomas J.; Vogler, William A.; and Baldasare, Paul: *Evaluation of Two Transport Aircraft and Several Ground Test Vehicle Friction Measurements Obtained for Various Runway Surface Types and Conditions*. NASA TP 2917, February 1990.
 10. Meyer, W.E.; Hegmon, R.R.; and Gillespie, T.D.: *Locked-Wheel Pavement Skid Tester Correlation and Calibration Techniques* . NCHRP Report No. 151, Transportation Research Board, 1974.
 11. Yager, Thomas J.; and Buhlman, F.: *Macrottexture and Drainage Measurements on a Variety of Concrete and Asphalt Surfaces*. Amer. Soc. of Testing and Materials, STP 763, pp.16 - 30, 1982.
 12. Leland, Trafford J.W.; Yager, Thomas J.; and Joyner, Upshur T.: *Effects of Pavement Texture on Wet Runway Braking Performance*. NASA TN D-4323, January 1968.
 13. Kak, Avinash C.; and Slaney, Malcolm: *Principles of Computerized Tomographic Imaging*. Institute of Electrical and Electronic Engineers, Inc. IEEE press, 1988

Table 1. Test surface description.		
Test Surface Number	Original surface	Description of Texture Modification
1	LG	Methacrylate, Double Coating
2	LG	Methacrylate, Single Coating
3	LG	Skidabrader™, 100 ft/min
4	TG	Skidabrader™, 100 ft/min
5	LG	Skidabrader™, 150 ft/min
6	TG	Skidabrader™, 150 ft/min
7	LG	Skidabrader™, 220 ft/min
8	TG	Skidabrader™, 220 ft/min
9	LG	Rotopeening, Longitudinal
10	TG	Rotopeening, Lateral
11	LG	Rotopeening, Longitudinal, New Belt
12	LG	Rotopeening, Longitudinal
13	TG	Rotopeening, Longitudinal
14	LG	Solid Head Cutter Diamond Grinding
15	TG	Solid Head Cutter Diamond Grinding
16	LG	Diamond Saw Grinding, 5 blades/inch
17	LG	None, Original Corduroy TD Zone
18	TG	None, Original Center Section

Table 2. Texture characterization measurements for test surfaces.						
Test Surface Number	Original surface	Description of Texture Modification	ATD, inches	BPT	BPT	Outflow Meter, sec
1	LG	Methacrylate, Double Coating	0.0056	41	37	
2	LG	Methacrylate, Single Coating	0.0123	75	48	
3	LG	Skidabrader™, 100 ft/min	0.0104	83	73	5.11
4	TG	Skidabrader™, 100 ft/min	0.0130	86	76	0.85
5	LG	Skidabrader™, 150 ft/min	0.0115	76	73	
6	TG	Skidabrader™, 150 ft/min	0.0159	86	83	0.77
7	LG	Skidabrader™, 220 ft/min	0.0119			4.63
8	TG	Skidabrader™, 220 ft/min	0.0136			0.90
9	LG	Rotopeening, Longitudinal	0.0083			
10	TG	Rotopeening, Lateral	0.0108	76	86	1.30
11	LG	Rotopeening, Longitudinal, New Belt	0.0104	75	65	
12	LG	Rotopeening, Longitudinal	0.0088			5.52
13	TG	Rotopeening, Longitudinal	0.0119			0.85
14	LG	Solid Head Cutter Diamond Grinding	0.0046			
15	TG	Solid Head Cutter Diamond Grinding	0.0062	56	76	3.20
16	LG	Diamond Saw Grinding, 5 blades/inch	0.0108	83	64	
17	LG	None, Original Corduroy TD Zone	0.0210	84	73	3.08
18	TG	None, Original Center Section	0.0192	88	84	0.91

Table 3. LSRA test conditions.

- (a). Nominal conditions.
- (b). Types of dispersions.
- (c). Case definitions.

- (a). **Nominal 20 kt crosswind tire conditions:**
Target touchdown speed: 205 kts
Derotation start at about 175 kts
Nominal tire peak load: 120000 lb
Centerline tracking; no steering

- (b). **Types of dispersions:**
- A. 225 kt touchdown speed**
 - B. Additional 0.4 degrees touchdown yaw to model drift**
 - C. Simulator error of 0.2 degrees additional slip near peak load time**
 - D. Aggressive steering; 3 degree additional yaw triangular pulse
4.5 sec long immediately after peak load**
 - E. High-rate derotation which increases tire vertical load to 142000 lb**
 - F. Right crosswind forcing vehicle to assume yaw to counter tire ply-steer
(extra 0.6 degrees at wheelstop)**



(c).

CASE	Nominal Landing PLUS Types of dispersions included:
9	A, B, C, E, F
10	A, B, C, D, E, F
11	A, B, C, D, E

Table 4. ITTV test surface wear summary.				
Test Surface Number	Description of Texture Modification	Wear Rate, lbm/ft	ATD, inches	
1	Methacrylate, Double Coating		0.0056	
2	Methacrylate, Single Coating	308.4E-6	0.0123	
3	Skidabrader™, 100 ft/min	330.4E-6	0.0104	
4	Skidabrader™, 100 ft/min	418.5E-6	0.0130	
5	Skidabrader™, 150 ft/min	330.4E-6	0.0115	
6	Skidabrader™, 150 ft/min	506.6E-6	0.0159	
7	Skidabrader™, 220 ft/min		0.0119	
8	Skidabrader™, 220 ft/min		0.0136	
9	Rotopeening, Longitudinal		0.0083	
10	Rotopeening, Lateral	242.3E-6	0.0108	
11	Rotopeening, Longitudinal, New Belt	330.4E-6	0.0104	
12	Rotopeening, Longitudinal		0.0088	
13	Rotopeening, Longitudinal	440.5E-6	0.0119	
14	Solid Head Cutter Diamond Grinding		0.0046	
15	Solid Head Cutter Diamond Grinding	198.2E-6	0.0062	
16	Diamond Saw Grinding, 5 blades/inch	418.5E-6	0.0108	
17	None, Original Corduroy TD Zone	616.7E-6	0.0210	
18	None, Original Center Section	594.7E-6	0.0192	

NASA KSC SHUTTLE LANDING FACILITY

MODIFIED SURFACE ARRANGEMENT



a. Original texture.



b. Corduroy texture.

TRANSVERSELY GROOVED
1/4 X 1/4 X 1 1/8 IN.

LONGITUDINAL GRINDING
4 1/2 BLADES/IN., CORDUROY FINISH

Figure 1. Kennedy Space Center Shuttle Landing Facility layout prior to testing.





Figure 2. The Instrumented Tire Test Vehicle (ITTV).



Figure 3. The Landing Systems Research Aircraft (LSRA).







Figure 5. Typical time histories of inputs for the LSRA test fixture.



a. ITTV test tires.

Figure 6. Test tires.



b. Orbiter main gear tire used during LSRA testing.

Figure 6. Concluded.






Figure 7. Cross-section of modified Orbiter main gear tire.



a. Mu-meter.

Figure 8. Other test vehicles.



b Skid trailer and tow vehicle.

Figure 8. Concluded.




Figure 9. British Pendulum Tester (BPT).





Figure 10. Outflow Meter.



Figure 11. Grease sample texture measurement kit.



Dimensions 1-40


▼ New ■ Worn

a. New versus worn tire profile comparison.


Figure 12. Computer tomography examples.

COMPUTED TOMOGRAPHY COMPARISON OF NEW AND WORN UNMOUNTED (LOOSE) T-38 TEST TIRE

New Unmounted



Worn Unmounted



b. Tire scan images.

Figure 12. Concluded.




Figure 13. KSC SLF test strip layout.
a. Overall layout





Figure 13. Continued
b. East ITTV test strips.



Numbers in circles denote test surface number

Figure 13. Continued
c. West ITTV test strips.




Figure 13. Concluded
d. LSRA test strips.




Figure 14. Diamond blade grinding machine.




Figure 15. Diamond blade grinding machine cutting heads.




Figure 16. Large diamond blade grinding machine.




Figure 17. Typical appearance of corduroy texture.

SKIDABRADER EQUIPMENT IN OPERATION




Figure 18. Skidabraderr™ machine.



a. Lateral application.

Figure 19. Rotopecner machine.




b. Surface after rotopeening.

Figure 19. Concluded.



a. Application to the corduroy surface.

Figure 20. Methacrylate coating.



b. Appearance of methacrylate after drying on surface.

Figure 20. Concluded.



Figure 21. Typical "bullseye" appearance of spin-up wear spot after cornering.




Figure 22. Tire wear behavior on modifications to the touchdown zone surface.




Figure 23. Relationship between wear rate and Average Texture Depth (ATD).




Figure 24. Tire wear behavior on modifications to the original center section surface.




Figure 25. Effect of speed on wet cornering performance for various textures.




Figure 26. Tire wear behavior on the existing KSC runway and the modified runway using the Skidabrader™




Figure 27. Tire side energy required for nominal 20 knot crosswind landing with and without piloting dispersions.




Figure 28. LSRA wear results on Test Strips 1 and 2.




Figure 29. LSRA wear results on Test Strips 1, 2, and 3.




Figure 30. Effect of speed on wet friction behavior on modified surfaces.




Figure 31. View of Skidabrader™ machines modifying entire SLF runway.

REPORT DOCUMENTATION PAGE			Form Approved OMB No. 0704-0188	
Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.				
1. AGENCY USE ONLY (Leave blank)		2. REPORT DATE July 1996		3. REPORT TYPE AND DATES COVERED Technical Memorandum
4. TITLE AND SUBTITLE Texture Modification of the Shuttle Landing Facility Runway at the NASA Kennedy Space Center			5. FUNDING NUMBERS WU 505-63-50-19	
6. AUTHOR(S) Robert Daugherty Thomas J. Yager				
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) NASA Langley Research Center Hampton, VA 23681-0001			8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES) National Aeronautics and Space Administration Washington, DC 20546-0001			10. SPONSORING / MONITORING AGENCY REPORT NUMBER NASA TM - 110269	
11. SUPPLEMENTARY NOTES				
12a. DISTRIBUTION / AVAILABILITY STATEMENT Unclassified - Unlimited Subject Category 05 07/ Availability: NASA CASI, (301) 621-0390			12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 200 words) This paper describes the test procedures and the selection criteria used in selecting the best runway surface texture modification at the Kennedy Space Center (KSC) Shuttle Landing Facility (SLF) to reduce Orbiter tire wear. The new runway surface may ultimately result in an increase of allowable crosswinds for launch and landing operations. The modification allows launch and landing operations in 20-kt crosswinds if desired. This 5-kt increase over the previous 15-kt limit drastically increases landing safety and the ability to make on-time launches to support missions where space station rendezvous is planned.				
14. SUBJECT TERMS Friction Macrotexture Texture Wear Tire			15. NUMBER OF PAGES 89	
			16. PRICE CODE A05	
17. SECURITY CLASSIFICATION OF REPORT Unclassified	18. SECURITY CLASSIFICATION OF THIS PAGE Unclassified	19. SECURITY CLASSIFICATION OF ABSTRACT Unclassified	20. LIMITATION OF ABSTRACT	